

**Portable Appliance Testing (PAT) Report**

**Debs Sweet Delights (PAT Testing Service)**

7 Willow Drive, St Marys Bay, New Romney, Kent. TN29 0SX.

**Report No.:**

DB-3 (page 1of4)

Test Instrument Seaward Primetest 100

**Date:**

10/06/2021

Customer Name

Dave Brazier 15 Pomfret Road,  
Chartham, Kent.

ID No.	Appliance Description	Appliance Location	Class: I,II,III. Ext'n lead IEC lead	Visual Inspect Pass or Fail	Fuse (A)	Test			Function Check	Test Pass or Fail	Date of Next Test	Comments
						Bond	Insulation	Leakage				
						RPE Ohms	RISO Mohms	I Leakage mA				
001	AC Adaptor	Output 15V	II	Pass	/	/	19.99	0.10	/	Pass		Unfused
002	IEC Lead 1M		IEC	Pass	13	0.05	19.99	/	/	Pass		
003	IEC Lead 2.5M		IEC	Pass	13	0.05	19.99	/	/	Pass		
004	Extension Lead 4M	2 Way	Ext	Pass	13	0.10	19.99	/	/	Pass		
005	AC Adaptor	Output 12V	II	Pass	/	/	19.99	0.10	/	Pass		Unfused
006												Item not found
007												Item not found
008	AC Adaptor	Output 9V	II	Pass	/	/	19.99	0.10	/	Pass		Unfused
009	Extension Lead 3M	4 Way	Ext	Pass	13	0.06	19.99	/	/	Pass		
010	Extension Lead 5M	4 Way	Ext	Pass	13	0.09	19.99	/	/	Pass		
011	I Phone Charger		II	Pass	/	/	19.99	0.10	/	Pass		Unfused
012	IEC Lead 1M		IEC	Pass	13	0.03	19.99	/	/	Pass		
013	IEC Lead 2M		IEC	Pass	13	0.05	19.99	/	/	Pass		
014	3 Way Adaptor		Ext	Pass	13	0.10	19.99	/	/	Pass		
015	Extension Lead 2M	4 Way	Ext	Pass	13	0.05	19.99	/	/	Pass		
016	Extension Lead 2M	4 Way	Ext	Pass	13	0.09	19.99	/	/	Pass		
017	I Phone Charger		II	Pass			19.99	0.10		Pass		Unfused
018												Item not found
019	IEC Lead 1.5M		IEC	Pass	5	0.04	19.99	/	/	Pass		
020												Item not found
021												Item not found
022	Extension Lead 5M	4 Way	Ext	Pass	13	0.10	19.99	/	/	Pass		
023	Extension Lead 5M	4 Way	Ext	Pass	13	0.10	19.99	/	/	Pass		
024												Item not found
025												Item not found

Total Appliances Tested.....49.....

Test Engineers Signature...*Don Eastgate*.....

Test Engineers Name .Don Eastgate.....

**Portable Appliance Testing (PAT) Report**

<p align="center"><b>Debs Sweet Delights (PAT Testing Service)</b> 7 Willow Drive, St Marys Bay, New Romney, Kent. TN29 0SX.</p>	<p align="center"><b>Report No.:</b></p>	DB-3 (page2of4)	<p align="center">Customer Name Dave Brazier 15 Pomfret Road, Chartham, Kent.</p>
	<p align="center">Test Instrument</p>	Seaward Primetest 100	
	<p align="center"><b>Date:</b></p>	10/06/2021	

ID No.	Appliance Description	Appliance Location	Class: I,II,III, Ext'n lead IEC lead	Visual Inspect	Fuse (A)	Test			Function Check	Test	Date of Next Test	Comments
						Bond	Insulation	Leakage				
						RPE Ohms	RISO Mohms	I Leakage mA				
026	Eurolive B112	Speaker	I	Pass	/	0.08	19.99	0.49	/	Pass		
027	Eurolive B112	Speaker	I	Pass	/	0.08	19.99	0.51	/	Pass		
028	Charger		II	Pass	/	/	19.99	0.10	/	Pass		Unfused
029	IEC Lead 2.5M		IEC	Pass	5	0.06	19.99	/	/	Pass		
030												Item not found
031												Item not found
032												Item not found
033												Item not found
034												Item not found
035												Item not found
036												Item not found
037												Item not found
038												Item not found
039	Charger		II	Pass	/	/	19.99	0.10	/	Pass		unfused
040												Item not found
041	Extension Lead 10M	4 Way	Ext	Pass	13	0.21	19.99	/	/	Pass		Adjusted Rpe
042	Charger		II	Pass	/	/	19.99	0.10	/	Pass		unfused
043												Item not found
044												Item not found
045	IEC Lead 2M		IEC	Pass	13	0.15	19.99	/	/	Pass		
046	LED Light Set		I	/	/	0.11	19.99	0.32	/	Pass		
047	Extension Lead 2M	4 Way	Ext	Pass	13	0.07	19.99	/	/	Pass		
048												Item not found
049												Item not found
050												Item not found

Total Appliances Tested.....49.....

Test Engineers Signature...*Don Eastgate*.....

Test Engineers Name .Don Eastgate.....

**Portable Appliance Testing (PAT) Report**

**Debs Sweet Delights (PAT Testing Service)**

7 Willow Drive, St Marys Bay, New Romney, Kent. TN29 0SX.

**Report No.:**

DB-3 (page3of4)

Test Instrument Seaward Primetest 100

**Date:**

10/06/2021

Customer Name

Dave Brazier 15 Pomfret Road,  
Chartham, Kent.

ID No.	Appliance Description	Appliance Location	Class: I, II, III, Ext'n lead IEC lead	Visual Inspect	Fuse (A)	Test			Function Check	Test Pass or Fail	Date of Next Test	Comments
						Bond	Insulation	Leakage				
				Pass or Fail		RPE Ohms	RISO Mohms	I Leakage mA				
051	Adaptor	2 Way	II	Pass		0.01	19.99	/		Pass		Unfused
052												Item not found
053	IEC Lead 1M		IEC	Pass	13	0.01	19.99	/		Pass		
054	LED Light	Par Can	I	Pass	13	0.11	19.99	0.21		Pass		
055	LED Light	Par Can	I	Pass	13	0.05	19.99	0.20		Pass		
056												Item not found
057	Charger		II	Pass	/	/	19.99	0.10		Pass		unfused
058	Charger		II	Pass	/	/	19.99	0.10		Pass		unfused
059	IEC Lead 3M		IEC	Pass	5	0.07	19.99	/		Pass		
060	Alesis Speaker		I	Pass	/	0.10	19.99	0.19		Pass		
061												Item not found
062	IEC Lead 3M		IEC	Pass	13	0.19	19.99	/		Pass		
063												Item not found
064	IEC Lead 4M		IEC	Pass	13	0.09	19.99	/		Pass		
065	LED Light		I	Pass	/	0.09	19.99	0.10		Pass		
066	LED Light		I	Pass	13	0.08	19.99	0.38		Pass		
067	IEC Lead 1M		IEC	Pass	13	0.04	19.99	/		Pass		
068												Item not found
069												Item not found
070	LED Light		I	Pass	/	0.07	19.99	0.49		Pass		
071	LED Light		I	Pass	5	0.02	19.99	0.19		Pass		
072												Item not found
073												Item not found
074												Item not found
075												Item not found

Total Appliances Tested.....49.....

Test Engineers Signature...*DEastgate*.....

Test Engineers Name .Don Eastgate.....

